

Meter Movement Inventory

	Scale	Size	Shape	Notes
	50 VDC	3 1/4"	R	
	Mini Meter	1 1/2"	R	2 Pcs
	RF Amp 8	3 1/2"	R	Open
	DC Ma ?	3 1/2"	R	
	DC Volts ?	3 1/4"	R	
	L. Gear Ind	1 1/4"	Rect Edge	
	1 Ma DC	3"	S	
11	Output db	1 "	R	2
12	Mini Ind	1/2"	R	
14	DC Amps 30-0-30	2 1/4"	R	
16	DC Ma 300	2 3/4"	R	
17	Oil Pres 75	2 1/2"	R	
18	DC Amps 80	2 1/4"	S	
19	DC Amps 30-0-30	2 1/4"	R	
			2	
20	VAC/Pres	2 1/4"	R	
23	RPM	2 3/4"	R	
24	DC Volts 30	2 1/4"	S	
25	DC Amps 40	2 1/4"	R	
27	Vacuum	3 3/4"	R	NOS
28	AC Amps 1	3 1/2"	S	Mounter in Mini Meter Cabinet
3	Thermo Couple	2 1/2"	R	?
3	FM Tuning	~2 "	S	
31	RF Amps 1.0	2 1/2"	R	NOS
32	RF Amps 2.5	3"	S	NOS
33	DC Ma 50	2 3/4"	R	Broken Glass
34	AC Ma 250	2 3/4"	R	
36	30/15 ?	3"	R	
37	AC Volts 40	2 1/2"	R	
39	DC Ma 1	2 1/2"	R	
4	? Ind	1/2 X 7/8"	Rect	
40	CarbTemp -10 +50	2 1/4"	R	
41	Motor Amps 5	3"	R	
42	db -10 +6	3 1/4"	R	
43	Volts/Amps	2 1/2"	R	
49	RF Amps 10	2 3/4"	R	
5	Level	2"	S	2 Pcs
52	DC Amps 15	3 1/2"	R	